

Fig. 1




Fig. 2




Fig. 3

2/6









Fig. 4















Fig. 9



Produce individual gold cap CAD-Casting-CAM	
Produce individual gold cap in the classical gold casting method	

2	Operational Group	Process	SSE	8 2	Operational Group	Process	ess	
<u> </u>		Manual Work	PC Work Machine	looT		Manuel Work	Automat	Work Machine Tool
_	Preparatory operations	×		-	Preparatory operations	×		
7	Deep draw foil cap	Σ		2	Optically measure stump by scanning		×	
(m	Adapt foil cap to stump	Σ		က	Automatic surface reconstruction		X	
4	Insulate stump	ᆇ		4	Construct crown cap CAD-3D		K	
വ	Fix foil cap	Σ		2	Automatically generate offset on CAD-3D model	-	×	
ဖ	Model crown in wax			9	Automatically generate CAM-NC program for coquille		Y	
7	Lacquer model	¥		7	Place coquille blank(s) in mounting bridge	¥		
∞	Prepare casting	Σ		8	5-axis mill coquille mould		×	×
თ	Prepare muffle	Σ		6	Automatically generate CAM-NC program for crown cap		×	
5	Produce bedding mass slurry	Σ		10		쏘		
=	Fine bedding in	エ		11	Cast coquille with noble metal or Co Cr Mo-alloy	Μ		
12	Bedding in	Σ		12		¥		
13	Wax out muffle and pre-warm		×	13	Mill out cavity side of the crown cap from the casting		×	×
14	Casting	エ		14	Backing embed cavity side	М		
15	Bedding out	Σ		15	Mill occlusal side		×	×
16	Finish clean cast blank	Σ		16	Release crown cap from bedding plastic	ᅩ		
17	Separate inlet channel	Σ		17	If appropriate, slightly manually correct crown cap	ᅩ		
18	Work with the hand piece	_		9	Blast crown cap	\mathbf{x}		
19	Blast crown cap	メ		19	Clean crown cap and stump	¥		
70	Clean crown cap and stump	ᅩ		8	Final operations	エ		
21	Final operations	×		_			_	
		; ;		_				
Σ	Manual Work Time Duration Short (K) Medium (M) Long (L)	M) mn) Long (L)	×		Fig. 7.	,	